



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT
Road History Data Sheet

General

Zone

YELAHANKA

Ward No.

2

Ward Name

Chowdeshwari Ward

Street ID

W0290, W0373

Street Name

NA, East Park Reje Lyt

Significant Landmark

western Side Kondappa layout

Segment No.

2/S-W0290/S103652

Total Length (m)

58.96

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	21.43	77.590238	13.112200	77.590333	13.112369	W0371	W0373
2	37.53	77.591178	13.108561	77.591521	13.108516	W0367	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work

Construction of CC road at 30th cross western Side Kondappa layout near Jangamaiah house in Ward no 02 of Yelahanka Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)

800000

Sanctioned Year

2016

Year

2016 - 2017

Type of Work

Road

Other Work Type

Tender

Not a Tender

Work Details

Construction of CC road at 30th cross western Side Kondappa layout near Jangamaiah house in Ward no 02 of Yelahanka Sub-Division Yelahanka zone

Job No. / Work Code

002-16-000032

Work Order No.

BBMP/EE (YNK.D)/WO/59/2016-17

Work Order Date

30/04/2016

Period of Extension

90 DAYS

Defect Liability Period From

29/12/2016

Defect Liability Period To

28/12/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor

KRIDL

Contractor Reg No (BBMP/PWD)

E-Mail ID

9449863065

Expenditure Booked / Released (Rs)

0.00

Zone: YELAHANKA

Ward No: 2

Ward Name: Chowdeshwari Ward

Street ID: W0290,
W0373

Date: 24/02/2017

Time: 23:17:46

RH20170224231746

Page 1 of 3

Field Inspection Details

Number of Trees

2

Any Other Information

Name

RAMANANJEEVAIAH

Date of Inspection

24/02/2017

Remarks

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA

Ward No: 2

Ward Name: Chowdeshwari Ward

Street ID: W0290,
W0373

Date: 24/02/2017

Time: 23:17:46

RH20170224231746

Page 2 of 3

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks				
Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAI AH	24/02/2017	26/03/2017	COMPLETED
SE	VASU K M	24/02/2017	26/03/2017	COMPLETED
EE	VASU K M	24/02/2017	26/03/2017	COMPLETED
AEE	G.B. PRABHAKAR	24/02/2017	26/03/2017	COMPLETED
AE	RAMANANJEEVAIAH	24/02/2017	26/03/2017	COMPLETED
AE	RAMANANJEEVAIAH	24/02/2017	26/03/2017	COMPLETED

Remarks				
Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAI AH	24/02/2017	26/03/2017	COMPLETED
SE	VASU K M	24/02/2017	26/03/2017	COMPLETED
EE	VASU K M	24/02/2017	26/03/2017	COMPLETED
AEE	G.B. PRABHAKAR	24/02/2017	26/03/2017	COMPLETED
AE	RAMANANJEEVAIAH	24/02/2017	26/03/2017	COMPLETED
AE	RAMANANJEEVAIAH	24/02/2017	26/03/2017	COMPLETED

Zone: YELAHANKA

Ward No: 2

Ward Name: Chowdeshwarl Ward

Street ID: W0290,
W0373

Date: 24/02/2017

Time: 23:17:46

RH20170224231746

Page 3 of 3